

Job Description

Minimum Qualifications:

Experience with Oxygen Acetylene Torch, Arc Welding, Wire Feed Welding, some fabrication, or formal training on these tasks. Entry level position; working under supervision.

- Cutting metal with torch, or plasma cutter
- Welding steel
- Metal Fabrication
- Grinding / weld preparation
- Removing/ Repairing / Replacing parts on equipment.